

Client  
Our Lady of the Wayside

Our Ref: Photo Report

Date: 1st September 2017

Dear John

### **Chimney Inspection Report**





Further to your instructions and your official order we are now pleased to confirm that all works of the above has been completed. We trust the work has been carried out to your satisfaction.





We enclose photos of the completed works for your records





Yours Faithfully



Grahame Stone  
Director

<u>Image/Item Number</u>	<u>Image</u>	<u>Description</u>
1		The full external shell was high pressure water jetted to remove all loose paint and traffic build-up
2		The full external shell was high pressure water jetted to remove all loose paint and traffic build-up
3		All minor cracks to external shell were ground out and recovered with new fiberglass matting.
4		All minor cracks to external shell were ground out and recovered with new fiberglass matting.

<u>Image/Item Number</u>	<u>Image</u>	<u>Description</u>
5		All internal bolts where replaced with new and tightened as the old ones where just hand tight.
6		. All internal bolts where replaced with new and tightened as the old ones where just hand tight.
7		The internal flange was cleaned and treated with stop rust inhibitor and two coats of paint applied
8		The internal flange was cleaned and treated with stop rust inhibitor and two coats of paint applied

<u>Image/Item Number</u>	<u>Image</u>	<u>Description</u>
9		New baffle was cut to size and fitted to prevent water ingress.
10		Cleaned external shell before paint application
11		Photo of completed job.
12		

## **Conclusions and Recommendations**

**We would recommend that spire is inspected every two years as a minimum of duty of care as the structure requires this due to its age.**



HIGH LEVEL MAINTENANCE  
RESTORATIONS  
LIGHTNING PROTECTION &  
FALL PROTECTION SAFETY  
SYSTEMS DIVISION



**HEAD OFFICE:** KELLAW ROAD | DARLINGTON | CO. DURHAM | DL1 4YA | **TEL:** 01325 282794 | **FAX:** 01325 487329

**Website:** [www.stonetechnicalgroup.co.uk](http://www.stonetechnicalgroup.co.uk) **Free Phone:** 0800 0480 151 **Email:** [enquiries@stoneservicesuk.com](mailto:enquiries@stoneservicesuk.com)

REGISTERED IN ENGLAND AND WALES No. 3912476